


# TigerShark®, TigerShark® QC, TigerShark® Plus

REPLACEMENT PARTS

## Parts Diagram



Cleaners

# TigerShark®, TigerShark® QC, TigerShark® Plus

REPLACEMENT PARTS

## Parts Listing

Ref. No.	Part No.	Description	Ctn. Qty.	List Price
1a	RCX97453	Power Supply-110VAC, TigerShark	1	<b>\$327.49</b>
1b	RCX3000RC	Power Supply-110VAC, TigerShark Plus	1	<b>571.65</b>
1c	RCX97453QC	Power Supply-110VAC, Quikclean	1	<b>374.49</b>
2a	RCX31013A	Power Supply Circuit Breaker 3A	50	<b>9.31</b>
2b	RCX31012	Power Supply Switch 16A	50	<b>4.95</b>
2c	RCX31012A	Power Supply Switch Membrane Cover	50	<b>14.31</b>
2d	RCX31018	Power Supply Output Connector	50	<b>34.47</b>
3	RCX76008-234	Handle Assembly - TS, TS Plus, TSQC, Blue	5	<b>47.72</b>
4	RCX11208BK	Venturi Assembly, Black	1	<b>24.55</b>
5	RCX12011	Screw, M5x20 T-20 (Set of 5)	10	<b>4.43</b>
6	RCX26001	Bearing, Guide Roller	10	<b>30.93</b>
7	RCX14000	Handle Arm Slide	10	<b>4.70</b>
8	RCX12001	Screw M4x12 T-20 (Set of 5)	10	<b>3.32</b>
9a	RCX11000	Impeller	10	<b>11.55</b>
9b	RCX12002	Screw M4x2 Flat Head T-15 (Set of 5)	10	<b>3.40</b>
10a	RCX75000-236	Bottom Lid Assembly, Black	1	<b>62.81</b>
10b	RCX78005	Bottom Lid Filter Gasket	10	<b>20.63</b>
10c	RCX75005	Inlet Flap	10	<b>4.28</b>
11a	RCX70101PAK2	Filter Cartridges (Set of 2)	5	<b>62.42</b>
11b	RCX70103PAK2	Spring Cleanup Filters (Set of 2)	5	<b>20.63</b>
12	RCX70100	Filter Cartridge Assembly, Frame and Filters	1	<b>94.23</b>
13a	RCX40000D	Motor Unit, Upgrade Kit for TigerShark AC	1	<b>889.95</b>
13b	RCX40000DC	Motor Unit, 4 hr. for TigerShark DC	1	<b>540.62</b>
13c	RCX43000	Motor Unit, 4 hr. for TigerSharkQC DC	1	<b>624.71</b>
13d	RCX4000RC	Motor Unit, 4 hr. for TigerShark Plus DC	1	<b>662.97</b>
14	RCX11400	Clip Lid (Set of 2)	10	<b>4.58</b>
15	RCX59006	Connector Socket, Molex	50	<b>2.04</b>
16	RCX59004	Seal Plug	10	<b>4.56</b>
17	RCX12302	Washer, Plastic Connector, Large Hole	10	<b>2.83</b>
18	RCX59003	Compression Plug	10	<b>6.50</b>
19	RCX12301	Washer, Plastic Connector, Small Hole	10	<b>2.83</b>
20	RCX59002	Connector Hosing	10	<b>4.28</b>
21	RCX23002	Drive Track, Soft Tread	5	<b>35.60</b>
22	RCX26000PAK2	Pulley Bearing Kit (Set of 2)	5	<b>20.68</b>
23	RCX26002	Bearing, Drive Pulley Assembly (Includes RC260031 insert)	10	<b>31.20</b>
24	RCX12100	Spring Handle Latch	10	<b>3.15</b>
25	RCX14100	Handle Latch	1	<b>5.66</b>
26a	RCX13220TS-237	Side Cover, TS (right and left)	1	<b>34.18</b>
26b	RCX13220TSP-237	Side Cover, TS Plus (right and left)	1	<b>34.18</b>
26c	RCX13220TSQC237	Side Cover, TSQC (right and left)	1	<b>34.18</b>
27a	RCX26008	Roller Brush	5	<b>26.40</b>
27b	RCX26011	Roller Foam with Tube	5	<b>39.32</b>
27c	RCX26003	Wheel Tube Assembly without Brush	5	<b>62.37</b>
27d	RCX26004	Wheel Tube	5	<b>11.03</b>
27e	RCX26005	Wheel Tube Bearing	10	<b>25.24</b>
27f	RCX3406	Wheel Tube Screws (Pack of 10)	10	<b>3.52</b>
28	RCX13001C	Main Case, TS, TSP, TSQC	1	<b>98.10</b>
29	RCX40117	Drive Pin Assembly	50	<b>10.74</b>
30a	RCX50061	Floating Cord Assembly - 55 ft. (TS, TSQC)	1	<b>167.29</b>
30b	RCX50110	Floating Cord Assembly - 100 ft. (TS2)	1	<b>294.24</b>
30c	RCX50070	Floating Cord Assembly - 55 ft. (TS Plus)	1	<b>352.95</b>
—	RCX97500GR	Drive Train Upgrade Kit	1	<b>127.37</b>
—	RCX17000	High Velocity Inlet	10	<b>9.04</b>
—	RCX11206	Restrictor Plate Kit	10	<b>4.19</b>
—	RCX11207	New Style Restrictor Plate	5	<b>9.31</b>
—	RCX40209	Hand-held Wireless Remote (2007 and Prior) 418 Mhz	1	<b>208.46</b>
—	RCX40215	Hand-held Wireless Remote (2008-present) 433 Mhz	10	<b>208.46</b>
—	RCX42000	Solenoid Assembly for Remote (TS Plus)	1	<b>178.12</b>

Cleaners